

DMR Association Interoperability Certificate Document **10038** www.dmrassociation.org

Note to readers: This DMR Association Interoperability Certificate documents that the ECOS-D RGW4000 product as detailed in Table A below:

TABLE A: DMR Equipment Tested		
Manufacturer	Leonardo Finmeccanica S.p.a	
Model	ECOS-D RGW4000	
Firmware	ID	Version
	ECOS-D RBS 4000	Rev 6.0.1.5

has successfully passed the DMR Association Tier III interoperability tests outlined in the DMR Association test specification document: Interoperability Testing for DMR Tier III Systems, Final 3.1, June 2016 on 15 June 2016 with the DP4801 product referenced in Table B below.

TABLE B: DMR Equipment Tested		
Manufacturer	Motorola Solutions	
Model	DP4801	
Firmware	ID	Version
	R02.60.05	R02.60.05

The DMR Association hereby declares that the product in Table A when tested with the product in Table B passed interoperability test cases as set out in the attached summary test report document 2016-005 Tier 3 Leonardo SYS RGW4000 and Motorola MS DP4801 Test Summary.

The DMR Association hereby declares that the testing took place according to the procedures and in a laboratory meeting the criteria set out in the DMR Association document: *Interoperability Laboratory Recognition Process and Test Session Procedures,* V2.01, May 2015

All products belonging to the same model classes, meaning equipment that Leonardo/Motorola Solutions have determined, through engineering analysis or internal functional testing, to be functionally equivalent to the products in Table A and Table B, may be declared interoperable by Leonardo and Motorola Solutions.

Issue Date: 28/12/2016

Chairman of the DMR Association Technical Working Group:

LIABILITY DISCLAIMER

The DMR Association declares that the IOP validation process has been carried out with the best possible endeavor in order to ensure the most reliable results. Nevertheless, the DMR Association takes no responsibility for, and shall have no liability as a result of damages, losses, or injuries of any kind that may be caused by non-conformance* of products that are awarded a DMR Interoperability Certificate.

Individual manufacturers are responsible for ensuring that the behavior of any equipment for which conformance is claimed is identical to that of the equipment that passed the DMR Association interoperability certification process.

*to the functions listed in the certificates